

ZyXEL Confidential



**Driver/Utility Release Note**

**AG-225H**

**Driver version: 1.35.0.0/2.1.0**

**Date:** OCT. 31, 2005

**Author:**

**Project Leader:**

# ZyXEL AG-225H Standard Version release 2.1.0 Released Note

**Date:** OCT. 31, 2005

## **Supported Platforms:**

---

Windows 2000, Windows XP

## **Versions:**

---

Driver Version : 1.35.0.0

Utility verison: 2.1.0

## **Known Issues:**

---

1. While the device is powering off, LCM will display random lines.
2. While wireless link is existed, same value of TX and RX speed rate is displayed on GUI.
3. Can not reject null SSID setting.
4. While an AG-225H connected to another AG-225H (software AP) with power saving mode enabled, the throughput is not high.
5. When hot swap the device many times in short period, the utility installed on notebook may not work properly.
6. Few kind of notebook may get blue screen when configuration the device with utility.

## **Features:**

---

### **Modifications in V 2.1.0 | 10/31/2005**

#### **1. Driver Changed.**

N/A

#### **2. Utility Changed.**

Rev 2.1.0b3 is the release candidate of Rev 2.1.0, and Rev 2.1.0 is released formally.

### **Modifications in V 2.1.0b3 | 10/19/2005**

#### **1. Driver Changed.**

N/A

#### **2. Utility Changed.**

1. [BUG FIX] After uninstall the device, INF file didn't be removed from notebook.

**ZyXEL Confidential**

2. [BUG FIX] Wireless link disconnect occasionally after restore from hibernate mode.
3. [BUG FIX] Wireless link disconnect occasionally with WPA-PSK and WPA2-PSK enabled, after restore from standby mode.

**Modification in 2.1.0b2 | 10/17/2005**

**1. Driver Changed.**

N/A

**2. Utility Changed.**

1. [BUG FIX] Remove oem.inf
2. [BUG FIX] Change web site to “www.ZyXEL.com” .
3. [BUG FIX] Fixed Add/Remove Program icon issue.

**Modification in 2.1.0b1 | 09/30/2005**

**1. Driver Changed.**

N/A

**2. Utility Changed.**

1. [BUG FIX] Remove 11a band on AdHoc mode on EU domain.