

VSG-1000 V1.04 Release Note:

VSG-1000 V1.03.08:

New Modifications:

1. "Dis-agree" change to "Do not agree"
2. The error message change to "Redirect Page URL link can't be empty" on User Agreement mode.
3. The warning message is "Sorry! Without accepting the policy, you may not access the Internet." by enter do not agree button.
4. The warning message is "Login successfully! To continue your Internet experience, please enter the URL of your choice in the address field above." by enter Agree button, when the portal page is not defined.

Fixed bug:

1. When we set radius, it connect error by user agreement mode.

VSG-1000 V1.03.07:

New Feature:

1. Add Portal Page at Advertisement Page.
2. Add User Agreement option and Redirect Page URL Link at Subscriber Control page.
3. When we type agree and dis-agree at User Agreement page by use User Agreement to login, the system must send syslog packet.
4. The device supports MSN 6.0

VSG-1000 V1.03.06:

New Modifications:

1. Super User username/password cannot be blank
2. Walled garden can only key-in one entry.
3. Remove FTP selection in the UI of Lan Device Management and add "Notice: The system does not support FTP"
4. Move "Super User Account" from under "Built-in Authentication" to under "Management Type"
5. Web Server Idle-timeout change from 20 minutes to be defined by administrator and default is 5 minutes.

VSG-1000 V1.03.05:

New Modifications:

1. Change "Proprietary" to "Built-in Authentication"

Fixed bug:

1. We login super user to connection internet, but connection will disconnect a short time.

VSG-1000 V1.03.04:

Fixed Bugs:

1. Password's max length is error in change password function by console.

VSG-1000 V1.03.03:

New Modifications:

1. Change Admin's default password to 1234.
2. Change no limited password, and the max length will be 30 characters (All Password).
3. Change WAN IP to default 192.168.1.1.
4. Change WAN Gateway to default 192.168.1.254.

VSG-1000 V1.03.02:

New Modifications:

1. Change "ZyXEL Subscriber Gateway" to "Vantage Service Gateway".
2. Firmware version number follows the previous ZSG-1000 number.

VSG-1000 V1.03.01:

New Modifications:

1. The password can not be blank for billing user to add.

Fixed Bugs:

1. Dhcp server assign duplicate ip on MAC os.
2. When DUT reboot for DHCP Client mode, it sometimes show error and reboot again.
3. Fixed Import Config will make system down.